

TROUBLE SHOOTING FOR TURNING

Trouble			Solution		Insert Grade Selection			Cutting Conditions				Style and Design of the Tool					Machine, Installation of Tool						
					Select a harder grade	Select a tougher grade	Select a grade with better thermal shock resistance	Select a grade with better adhesion resistance	Cutting speed	Feed	Depth of cut	Coolant		Select chip breaker	Rake	Corner radius	Lead angle	Honing strengthens the cutting edge	Class of insert	Improve tool holder rigidity	Increase clamping rigidity of the tool and workpiece	Decrease holder overhang	Decrease power and machine backlash
			Up ↗ Down ↘	Do not use water-soluble cutting Determine dry or wet cutting								Up ↗ Down ↘											
Factors																							
Deterioration of Tool Life	Insert wear quickly generated	Improper tool grade	a																				
		Improper cutting edge geometry											a	↗ a	↗ a	↗ a	↘ a						
		Improper cutting speed					↘ a	↗ a			a Wet												
	Chipping or fracturing of cutting edge	Improper tool grade		a																			
		Improper cutting conditions						↘ a	↘ a														
		Lack of cutting edge strength.										a		↗ a		↗ a							
		Thermal crack occurs			a		↘ a	↘ a	↘ a	a	a Dry												
Build-up edge occurs					a	↗ a	↗ a		a	a Wet													
Lack of rigidity																	a	a	a	a			
Out of Tolerance	Dimensions are not constant	Poor insert accuracy															a						
		Large cutting resistance and cutting edge flank											a	a	↘ a	↘ a	↘ a		a	a	a	a	
	Necessary to adjust often because of over-size	Improper tool grade	a																				
		Improper cutting conditions					↘ a	↗ a															
Deterioration of Surface Finish	Poor finished surface	Welding occurs					↗ a			a	a Wet												
		Improper cutting edge geometry										a		↗ a									
		Chattering					↘ a	↘ a	↘ a									a	a	a	a		
Generation of Heat	Workpiece over heating can cause poor accuracy and short life of insert	Improper cutting conditions					↘ a	↘ a	↘ a														
		Improper cutting edge geometry											a	↗ a		↘ a							

TECHNICAL DATA

Trouble			Solution		Insert Grade Selection		Cutting Conditions				Style and Design of the Tool						Machine, Installation of Tool						
			Factors		Select a harder grade	Select a tougher grade	Select a grade with better thermal shock resistance	Select a grade with better adhesion resistance	Cutting speed	Feed	Depth of cut	Coolant		Select chip breaker	Rake	Corner radius	Lead angle	Honing strengthens the cutting edge	Class of insert	Improve tool holder rigidity	Increase clamping rigidity of the tool and workpiece	Decrease holder overhang	Decrease power and machine backlash
												Do not use water-soluble cutting	Determine dry or wet cutting										
							Up ↗		Down ↘				Up ↗				Down ↘						
Burrs, Chipping etc.	Burrs (steel, aluminium)	Notch wear	a																				
		Improper cutting conditions					a ↘	a ↗			a Wet												
		Improper cutting edge geometry										a	a ↗	a ↘	a ↘	a ↘							
	Workpiece chipping (cast iron)	Improper cutting conditions						a ↘	a ↘														
		Improper cutting edge geometry										a	a ↗	a ↗	a ↗	a ↘							
		Vibration occurs																	a	a	a	a	
	Burrs (mild steel)	Improper tool grade				a																	
		Improper cutting conditions					a ↗			a	a Wet												
		Improper cutting edge geometry										a	a ↗			a ↘							
		Vibration occurs																	a	a	a	a	
Poor Chip Dispersal	long chips	Improper cutting conditions					a ↘	a ↗	a ↗		a Wet												
		Large chip control range										a											
		Improper cutting edge geometry												a ↘	a ↘								
	Chips are short and scattered	Improper cutting conditions						a ↘	a ↘		a Dry												
		Small chip control range										a											
		Improper cutting edge geometry												a ↗	a ↗								

TROUBLE SHOOTING FOR FACE MILLING

Trouble			Solution		Insert Grade Selection				Cutting Conditions					Style and Design of the Tool								Machine, Installation of Tool			
					Select a harder grade	Select a tougher grade	Select a grade with better thermal shock resistance	Select a grade with better adhesion resistance	Cutting speed	Feed	Depth of cut	Engage angle	Coolant		Rake	Corner angle	Honing strengthens the cutting edge	Cutter diameter	Number of teeth	Wider chip pocket	Use of a wiper insert	Improve run-out accuracy	Cutter rigidity	Increase clamping rigidity of the tool and workpiece	Decrease overhang
			Do not use water-soluble cutting fluid	Determine dry or wet cutting									Up ↗ Down ↘	Up ↗ Down ↘											
Factors							Up ↗ Down ↘		Up			Up ↗ Down ↘													
Deterioration of Tool Life	Insert wear quickly generated	Improper tool grade	a											↗ a	↗ a	↘ a									
		Improper cutting edge geometry												↗ a	↗ a	↘ a				a					
		Improper cutting speed					↘ a					a Wet													
	Chipping or fracturing of cutting edge	Improper tool grade		a																					
		Improper cutting conditions						↘ a	↘ a								↗ a								
		Lack of cutting edge strength.															↗ a								
		Thermal crack occurs			a		↘ a	↘ a	↘ a		a	a Dry													
Build-up edge occurs				a	↘ a	↘ a			a	a Wet															
Lack of rigidity																				a	a	a	a		
Deterioration of Surface Finish	Poor finished surface	Improper cutting conditions	a				↘ a	↘ a	↘ a					↗ a											
		Welding occurs				a	↘ a				a	a Wet	↗ a			↘ a									
		Poor run-out accuracy																	a	a					
		Chattering					↘ a	↘ a	↘ a	↗ a			↗ a		↘ a		↘ a					a	a	a	a
	Not parallel or irregular surface	Workpiece bending						↘ a	↘ a				↗ a	↘ a	↘ a		↘ a						a		
		Tool clearance																				a	a	a	a
		Large back force												↗ a	↘ a	↘ a		↘ a							
Burr, Workpiece Chipping	Burrs, chipping	Chip thickness is too large					↗ a	↘ a	↘ a																
		Cutter diameter is too large								↗ a						↘ a									
		Low sharpness											↗ a			↘ a									
		A large corner angle												↘ a											
	Workpiece edge chipping	Improper cutting conditions						↘ a	↘ a				↗ a				↘ a								
		Low sharpness											↗ a			↘ a									
		A small corner angle												↗ a											
		Chattering					↘ a	↘ a	↘ a	↗ a			↗ a		↘ a		↘ a					a	a	a	a
Chip Control	Poor chip dispersal, chip jamming and chip packing	Welding occurs					↘ a																		
		Chip thickness is too thin					↗ a	↗ a																	
		Cutter diameter is too small														↘ a									
		Poor chip disposal									a	a Wet					↘ a	a							

TROUBLE SHOOTING FOR END MILLING








Solution			Insert Grade Selection	Cutting Conditions									Style and Design of the Tool				Machine, Installation of Tool							
				Coated tool	Cutting speed		Feed	Depth of cut	Pick feed	Down cut	Use air blow	Coolant			Helix angle	Insert number	Concavity angle of end cutting edge	Tool diameter	Cutter rigidity	Wider chip pocket	Shorten tool overhang	Increase tool installation accuracy	Increase spindle collet run-out accuracy	Collet inspection and exchange power
			Up ↗ Down ↘				Increase coolant quantity	Do not use water-soluble cutting				Determine dry or wet cutting	Up ↗ Larger Down ↘ Smaller											
Trouble	Factors																							
Deterioration of Tool Life	Large peripheral cutting edge wear	Non-coated end mill is used	a																					
		A small number of cutting edges												↗ a										
		Improper cutting conditions		↘ a							a													
		Up cut milling is used						Down Cut																
	Severe chipping	Improper cutting conditions																						
		Fragile cutting edge															a							
		Insufficient clamping force																				a	a	
		Low clamping rigidity																	a	a	a	a	a	a
	Breakage during cutting	Improper cutting conditions				↘ a																		
		Low end mill rigidity														↗ a	a							
		Overhang longer than necessary				↘ a														a				
		Chip jamming								a								a						
Deterioration of Surface Finish	Vibration during cutting	Improper cutting conditions		↘ a	↘ a								↗ a	↗ a		↗ a	a							
		Low end mill rigidity												↗ a										
		Low clamping rigidity																	a	a	a	a	a	a
	Poor surface finish on walls	Large cutting edge wear	a																					
		Improper cutting conditions		↘ a		↘ a																		
		Chip packing.							a	a		a Wet												
	Poor surface finish on faces	The end cutting edge does not have a concave angle			↘ a	↘ a									↗ a									
		Large pick feed					↘ a																	
		Out of vertical	Large cutting edge wear	a																				
	Improper cutting conditions				↘ a	↘ a								↗ a	↗ a		↗ a	a						
	Lack of end mill rigidity													↗ a										
	Poor dimensional accuracy	Improper cutting conditions		↘ a	↘ a	↘ a																		
Low clamping rigidity																			a	a	a	a	a	
Burrs, Chipping, etc.	Burr or chipping occurs	Improper cutting conditions			↘ a	↘ a																		
		Large helix angle											↘ a											
	Quick bur formation	Notch wear	a																					
		Improper cutting conditions		↘ a	↗ a																			
Poor Chip Dispersal	Chip packing	Metal removal too large			↘ a	↘ a																		
		Lack of chip pocket												↘ a				a						

TROUBLE SHOOTING FOR DRILLING

Solution Trouble Factors			Cutting Conditions									Style and Design of the Tool						Machine, Installation of Tool					
			Cutting speed	Feed	Lower feed at initial cutting	Lower feed when breaking through	Step feed	Increase accuracy of prep-hole and depth	Coolant			Chisel width	Honing width	Core thickness	Shorten flute length	Decrease lip height	Use internal coolant type drill	Change to a drill with X type thinning	Increase tool installation accuracy	Shorten tool overhang	Flat workpiece face	Increase work clamping rigidity	Reduce machine backlash and increase rigidity
									Increase oil ratio	Increase volume	Increase coolant pressure												
			Up ↗	Down ↘								Up ↗	Down ↘										
Deterioration of Tool Life	Drill breakage	Lack of drill rigidity												↗ a	a								
		Improper cutting conditions		↘ a																			
		Large deflection of the tool holder																a				a	
		Workpiece face is inclined																		a			
	Large wear at the peripheral cutting edge and along the land	Improper cutting conditions	↘ a														a						
		An increase in temperature at the cutting point							a	a						a							
	Chipping of the peripheral cutting edge	Poor run-out accuracy																a					
		Improper cutting conditions		↘ a			a																
	Chisel edge chipping	Large deflection of the tool holder																a				a	
		chattering, vibration											↘ a						a		a	a	
The chisel edge width is too wide												↘ a											
Deterioration of Hole Accuracy	Hole diameter increases	Poor entry			a																		
		Chattering, vibration											↘ a						a		a	a	
	Hole diameter becomes smaller	Lack of drill rigidity												↗ a	a								
		Improper drill geometry														a							
	Poor straightness	An increase in temperature at the cutting point							a	a						a							
		Improper cutting conditions	↘ a																				
	Poor hole positioning accuracy, roundness and surface finish	Improper drill geometry														a							
		Lack of drill rigidity												↗ a	a								
Poor entry																a							
Improper cutting conditions				a																			
Burrs	Burrs at the hole exit	Large deflection of the tool holder																					
		Large deflection of the tool holder																a			a		
Poor Chip Dispersal	Long chips	Lack of drill rigidity												↗ a	a								
		Poor entry															a						
	Chip jamming	Improper cutting conditions	↘ a	↘ a				a															
		Poor chip disposal							a	a				↘ a			a						

TOOL WEAR AND DAMAGE

CAUSES AND COUNTERMEASURES

Tool Damage Form		Cause	Countermeasure
Flank Wear		• Tool grade is too soft. • Cutting speed is too high. • Flank angle is too small. • Feed rate is extremely low.	• Tool grade with high wear resistance. • Lower cutting speed. • Increase flank angle. • Increase feed rate.
Crater Wear		• Tool grade is too soft. • Cutting speed is too high. • Feed rate is too high.	• Tool grade with high wear resistance. • Lower cutting speed. • Lower feed rate.
Chipping		• Tool grade is too hard. • Feed rate is too high. • Lack of cutting edge strength. • Lack of shank or holder rigidity.	• Tool grade with high toughness. • Lower feed rate. • Increase honing. (Round honing is to be changed to chamfer honing.) • Use large shank size.
Fracture		• Tool grade is too hard. • Feed rate is too high. • Lack of cutting edge strength. • Lack of shank or holder rigidity.	• Tool grade with high toughness. • Lower feed rate. • Increase honing. (Round honing is to be changed to chamfer honing.) • Use large shank size.
Plastic Deformation		• Tool grade is too soft. • Cutting speed is too high. • Depth of cut and feed rate are too large. • Cutting temperature is high.	• Tool grade with high wear resistance. • Lower cutting speed. • Decrease depth of cut and feed rate. • Tool grade with high thermal conductivity.
Welding		• Cutting speed is low. • Poor sharpness. • Unsuitable grade.	• Increase cutting speed. (For JIS S45C, cutting speed 80m/min.) • Increase rake angle. • Tool grade with low affinity. (Coated grade, cermet grade)
Thermal Cracks		• Expansion or shrinkage due to cutting heat. • Tool grade is too hard. ★Especially in milling.	• Dry cutting. (For wet cutting, flood workpiece with cutting fluid) • Tool grade with high toughness.
Notching		• Hard surfaces such as uncut surfaces, chilled parts and machining hardened layer. • Friction caused by jagged shape chips. (Caused by small vibration)	• Tool grade with high wear resistance. • Increase rake angle to improve sharpness.
Flaking		• Cutting edge welding and adhesion. • Poor chip disposal.	• Increase rake angle to improve sharpness. • Enlarge chip pocket.
Flank Wear Fracture		• Damage due to the lack of strength of a curved cutting edge.	• Increase honing. • Tool grade with high toughness.
★Damage for polycrystallines			
Crater Wear Fracture		• Tool grade is too soft. • Cutting resistance is too high and causes high cutting heat.	• Decrease honing. • Tool grade with high wear resistance.
★Damage for polycrystallines	